

Inspection Photos

Loc#324047

Operator: Terra

Insp#:692403191

Insp Date: 3/5/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

March 5, 2021




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos: Terra Clough Loc#324047



Photo#2:
Interim area.



Photo#3:
.Interim area.

March 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos: Terra Clough Loc#324047