

Inspection Photos
Operator: Simcoe
API: 067-07373
Date: 3/10/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Perennial vegetation observed is in a grazed condition and needs to be monitored during the active growing season to ensure site stabilization.



Photo 3. View of horse pasture that is largely dormant and grazed at this time.



Photo 4. View of closed gate after leaving location.