

Inspection Photos
Operator: Simcoe
API: 067-09662
Date: 3/10/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area facing westward from the southeastern corner. Revegetation is progressing with grasses such as blue grama and crested wheatgrass.



Photo 3. View of the eastern project area facing northward.



Photo 4. View of reference area comprised of open pinyon-juniper woodland with sagebrush and western wheatgrass, blue grama, and other grasses forbs in a dormant condition.