


**Inspection Photos**  
**Location Name: Kunce 1-20**  
**Location ID: 319653**

Mar 11, 2021 at 3:33:09 PM  
39.955322,-104.125632  
COGCC



**Pic 1 unused equipment**

Mar 11, 2021 at 3:34:06 PM  
39.955229,-104.125626  
2930 E 144th Ave  
Viggin CO 80654  
United States  
COGCC



**Pic 2 Unused equipment**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Kuncce 1-20**  
**Location ID: 319653**



**Pic 3**