

Inspection Photos
Operator: Simcoe
API: 067-06780
Date: 3/10/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area facing westward from the southeastern corner. Revegetation is progressing with grasses such as western wheatgrass and rubber rabbitbrush.



Photo 3. View of the western project area facing northward from the southwestern corner.



Photo 4. View of reference area comprised of open pinyon-juniper woodland with sagebrush and western wheatgrass, blue grama, and other grasses forbs in a dormant condition.