

Inspection Photos
Operator: Simcoe
Facility: 159078
Date: 3/10/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern well pad fill slope facing westward. Per FIR Resolution form, area was seeded in 2020. Due to early season dormant vegetation condition, seeding success was not determined.



Photo 3. View of the eastern project area facing northward.



Photo 4. View of reference area comprised of irrigated grass field with smooth brome.