

Inspection Photos

Loc#4202231

Operator: Terra

Insp#: 692403211

Insp Date: 3/11/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

March 11, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos:Terra McLin Loc#4202231



Photo#2:
Interim area.

March 11, 2021



Photo#3:
DG Well API#045-20136

Insp Photos:Terra McLin Loc#4202231