

Inspection Photos

Loc#416722

Operator: Terra

Insp#: 692403212

Insp Date: 3/11/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

March 11, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos: Terra Mclin B Loc#416722



Photo#2:
Interim area.



Photo#3:
Interim area

March 11, 2021




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos: Terra Mclin Loc#416722



Photo#4:
Escape Boards in cellars not adjusted properly.

March 11, 2021



Photo#5:
Escape Boards in cellars not adjusted properly.