

Inspection Photos

Location Name: DF Ranch 10-11, 13, 42, 44 Tank Battery

Location ID: 460765



Photo 1 – Tank Battery Sign

Photo 2 – Tank Battery

Inspection Photos

Location Name: DF Ranch 10-11, 13, 42, 44 Tank Battery

Location ID: 460765



Photo 3 – Treaters and ECD

Photo 4 – 100 BBL Pit – Capacity has Faded