

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/11/2021

Submitted Date:

03/16/2021

Document Number:

692403212**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 416722      Colby, Lou      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 950 17TH STREET, SUITE 1900City: DENVER      State: CO      Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416837	WELL	DG	10/08/2019	LO	045-19372	McLin B2	RI
416839	WELL	PR	07/02/2014	GW	045-19373	McLin B19	RI
416840	WELL	DG	10/08/2019	LO	045-19374	McLin B14	RI
416842	WELL	PR	10/29/2012	GW	045-19375	McLin B9	RI
416843	WELL	PR	03/30/2015	OW	045-19376	McLin B6	RI
416844	WELL	PR	01/17/2012	GW	045-19377	McLin B3	RI
416845	WELL	DG	10/08/2019	LO	045-19378	McLin B1	RI
416848	WELL	PR	01/17/2012	GW	045-19379	McLin B7	RI
416849	WELL	PR	01/24/2014	GW	045-19380	McLin B11	RI
416851	WELL	PR	01/19/2014	GW	045-19381	McLin B17	RI
416852	WELL	PR	01/19/2014	GW	045-19382	McLin B15	RI
416855	WELL	PR	01/19/2014	GW	045-19383	McLin B20	RI
416856	WELL	PR	01/19/2014	GW	045-19384	McLin B16	RI
416858	WELL	DG	10/08/2019	LO	045-19385	McLin B12	RI
416859	WELL	DG	10/08/2019	LO	045-19386	McLin B10	RI
416860	WELL	PR	07/02/2014	GW	045-19387	McLin B8	RI
416861	WELL	DG	10/08/2019	LO	045-19388	McLin B13	RI
416862	WELL	PR	10/29/2012	GW	045-19389	McLin B5	RI
416863	WELL	PR	03/30/2015	OW	045-19390	McLin B4	RI
416864	WELL	PR	07/02/2014	GW	045-19391	McLin B18	RI
434060	WELL	PR	06/15/2016	OW	045-22156	McLin B21	RI

**General Comment:**

This is an Interim Reclamation & Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed remain applicable.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	#		corrective date
Comment:	#s of Wildlife Escape Boards in cellars (especially DG Wells) are not adjusted properly; not in position to allow means of Wildlife egress. Boards are at too steep an angle (may need longer boards).		
Corrective Action:	Adjust boards at an angle to allow egress by wildlife. Options for DG Wells would be to fully cover cellars, or fill in cellars.		Date: <u>03/30/2021</u>

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date: <input type="text"/>

**Flaring:**

Type		
Comment:		
Corrective Action:		Date: <input type="text"/>

Inspected Facilities				
Facility ID: <u>416837</u>	Type: <u>WELL</u>	API Number: <u>045-19372</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416839</u>	Type: <u>WELL</u>	API Number: <u>045-19373</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416840</u>	Type: <u>WELL</u>	API Number: <u>045-19374</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416842</u>	Type: <u>WELL</u>	API Number: <u>045-19375</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416843</u>	Type: <u>WELL</u>	API Number: <u>045-19376</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416844</u>	Type: <u>WELL</u>	API Number: <u>045-19377</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416845</u>	Type: <u>WELL</u>	API Number: <u>045-19378</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416848</u>	Type: <u>WELL</u>	API Number: <u>045-19379</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416849</u>	Type: <u>WELL</u>	API Number: <u>045-19380</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416851</u>	Type: <u>WELL</u>	API Number: <u>045-19381</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416852</u>	Type: <u>WELL</u>	API Number: <u>045-19382</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416855</u>	Type: <u>WELL</u>	API Number: <u>045-19383</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416856</u>	Type: <u>WELL</u>	API Number: <u>045-19384</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416858</u>	Type: <u>WELL</u>	API Number: <u>045-19385</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416859</u>	Type: <u>WELL</u>	API Number: <u>045-19386</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416860</u>	Type: <u>WELL</u>	API Number: <u>045-19387</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416861</u>	Type: <u>WELL</u>	API Number: <u>045-19388</u>	Status: <u>DG</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416862</u>	Type: <u>WELL</u>	API Number: <u>045-19389</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>416863</u>	Type: <u>WELL</u>	API Number: <u>045-19390</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>

Facility ID:	416864	Type:	WELL	API Number:	045-19391	Status:	PR	Insp. Status:	RI
Facility ID:	434060	Type:	WELL	API Number:	045-22156	Status:	PR	Insp. Status:	RI

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: <b>RANGELAND</b>	
Reminder: _____	
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Well plugged _____ Debris removed _____ Access Roads _____ Regraded _____ Gravel removed _____	Pit mouse/rat holes, cellars backfilled _____ No disturbance /Location never built _____ Contoured _____ Culverts removed _____ Locations, facilities, roads, recontoured _____ Dust and erosion control _____ Cropland: perennial forage _____
Location and associated production facilities reclaimed _____	
Compaction alleviation _____	
Non cropland: Revegetated 80% _____	
Weeds present _____      Subsidence _____	
1004.d. FINAL VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Corrective Action: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>	
Date _____	
Overall Final Reclamation _____	Well Release on Active Location <input type="checkbox"/>
Multi-Well Location <input type="checkbox"/>	

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692403223	Inspection Photos RI	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5377354">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5377354</a>