

FORM

21

Rev
11/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402627168

Date Received:

MECHANICAL INTEGRITY TEST

1. Duration of the pressure test must be a minimum of 15 minutes.
2. An original pressure chart must accompany this report if this test was not witnessed by an OGCC representative.
3. For production wells, test pressures must be at a minimum of 300 psig.
4. New injection wells must be tested to maximum requested injection pressure.
5. For injection wells, test pressures must be at least 300 psig or average injection pressure, whichever is greater.
6. A minimum 300 psi differential pressure must be maintained between the tubing and tubing/casing annulus pressure.
7. Do not use this form if submitting under provisions of Rule 326.a(1)B. or C.
8. Written OGCC notification must be provided 10 days prior to the test via Form 42, Field Operations Notice
9. Packers or bridge plugs, etc., must be set within 100 feet of the perforated interval to be considered a valid test.

Complete the Attachment

Checklist

OP OGCC

OGCC Operator Number: 74165	Contact Name: Edward Ingve	Pressure Chart		
Name of Operator: RENEGADE OIL & GAS COMPANY LLC	Phone: (303) 829-2354	Cement Bond Log		
Address: 6155 S MAIN STREET #225		Tracer Survey		
City: AURORA State: CO Zip: 80016 Email: ed@renegadeoilandgas.com		Temperature Survey		
API Number: 05-001-07206	OGCC Facility ID Number: 201802	Inspection Number		
Well/Facility Name: BRADBURY B	Well/Facility Number: 1			
Location QtrQtr: SWNW Section: 14 Township: 2S Range: 60W Meridian: 6				

☒ SHUT-IN PRODUCTION WELL ☐ INJECTION WELL Last MIT Date: _____

Test Type:

☒ Test to Maintain SI/TA status ☐ 5-Year UIC ☐ Reset Packer

☐ Verification of Repairs ☐ Annual UIC TEST

☐ Describe Repairs or Other Well Activities: SI Third Creek Gas Gathering System well. Well did not qualify for alternative MIT procedure due to high bradenhead pressure.

Wellbore Data at Time of Test				Casing Test Use when perforations or open hole is isolated by bridge plug or cement plug; use if cased-hole only with plug back total depth. Bridge Plug or Cement Plug Depth 6318
Injection Producing Zone(s)	Perforated Interval	Open Hole Interval		
JSND	6356'-6372'			
Tubing Casing/Annulus Test				
Tubing Size:	Tubing Depth:	Top Packer Depth:	Multiple Packers?	
			<input type="checkbox"/>	

Test Data (Use -1 for a vacuum)

Test Date	Well Status During Test	Casing Pressure Before Test	Initial Tubing Pressure	Final Tubing Pressure
03-12-2021	SHUT-IN	0		
Casing Pressure Start Test	Casing Pressure - 5 Min.	Casing Pressure - 10 Min.	Casing Pressure Final Test	Pressure Loss or Gain
468	467	465	464	-4

Test Witnessed by State Representative? ☐ OGCC Field Representative Medina, Justin

OPERATOR COMMENTS:

Mechanical Integrity Test was performed on the Bradbury B-1 as a requirement of Warning Letter document number 402491859 issued 9/17/2020. The Bradbury B-1 did not qualify for the alternative MIT procedure developed with COGCC staff that the other warning letter referenced wells received due to elevated bradenhead pressure found on the Bradbury B-1. Now that the well's casing successfully has demonstrated integrity a plan will be discussed with COGCC staff to address the high bradenhead pressure.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Edward Ingve
Title: Manager/Owner Email: ed@renegadeoilandgas.com Date: _____

Based on the information provided herein, this Notice (Form 21) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY:

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
402630138	PRESSURE CHART

Total Attach: 1 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)