

# *Inspection Photos*

*Loc#335173*

*Operator: Grizzly*

*Insp#: 692403216*

*Insp Date: 3/11/21*





Photo#1:  
Overview of Location and insert of interim vegetation.

March 11, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Grizzly Jolley Loc#335173



Photo#2:  
Cut slope at east side of site.



Photo#3:  
Cut slope at east side of site.

March 11, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Grizzly Jolley Loc#335173