

Inspection Photos  
Location Name: Pevler 14-22  
Location ID: 410064



Photo 1 – Wellhead Sign, Stained Soil at Exhaust

Photo 2 – Wellhead

**Inspection Photos**  
**Location Name: Pevler 14-22**  
**Location ID: 410064**



Colorado Oil and Gas Conservation Commission  
40.92709, -104.17963, 5239.4ft, 182°  
03/10/2021 13:09:32

**Photo 3 – Pumping Unit**