

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action: _____

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	<u>Wire</u>		
Corrective Action:		Date:	

Equipment:

Type		#		corrective date
Gas Meter Run		# 1		
Comment:				
Corrective Action:			Date:	
Emission Control Device		# 1		
Comment:				
Corrective Action:			Date:	
Other		#		
Comment:	<u>Riser in-between Crude oil tank and pit is unmarked.</u>			
Corrective Action:	<u>Comply with Rule 1102.o</u>		Date:	<u>03/26/2021</u>
Bird Protectors		# 2		
Comment:				
Corrective Action:			Date:	
Horizontal Heated Separator		# 1		
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		

Comment: [Shares containment with crude oil tank.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	
Other (Content)	
Other (Capacity)	60 BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.279900,-104.527800

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 447614 Type: TANK API Number: - Status: AC Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 3/11/21 at approximately 0705hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Lehfeltd C 27-15, 16 Tank Battery of Noble Energy, at Facility ID # 447614 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Riser in-between Crude oil tank and pit is unmarked. Comply with Rule 1102.o. With a corrective action date of 3/26/21 See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	03/11/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402625954	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5373979
699103251	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5373952