

## Inspection Photos

Location Name: CAERUS PICEANCE LLC RAMOS-68S96W /1NESW

Location ID: 334104



**Photo #3170 from entrance to location.**



**Photo #3171 from entrance to location**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC RAMOS-68S96W /1NESW

Location ID: 334104



**Photo #3172 Multiple holes in tank containment liner.**



**Photo #3173 Multiple holes in tank containment liner.**