

Inspection Photos

Location Name: CAERUS PICEANCE LLC DUTTON FAMILY LIMITED-68S96W /1SESE,

Location ID: 334368



Photo #3175 Access road off of county road 306.



Photo #3177 Tracking occurring from Caerus access road on to county road 306.

Inspection Photos

Location Name: CAERUS PICEANCE LLC DUTTON FAMILY LIMITED-68S96W /1SESE,

Location ID: 334368



Photo #3178 Tracking occurring from Caerus access road on to county road 306.



Photo #3179 Sediment has been transported from access road on to county road for approximately 100 yards.

Inspection Photos

**Location Name: CAERUS PICEANCE LLC DUTTON FAMILY LIMITED-68S96W /1SESE,
Location ID: 334368**



Photo #3180 Sediment has been transported from access road on to county road for approximately 100 yards.



Photo #3181 Sediment from county road has migrated into ditch.

Inspection Photos

**Location Name: CAERUS PICEANCE LLC DUTTON FAMILY LIMITED-68S96W /1SESE,
Location ID: 334368**



Photo #3182 Sediment from county road has migrated into ditch.




Photo #3176 Tracking controls insufficient

Inspection Photos

Location Name: CAERUS PICEANCE LLC DUTTON FAMILY LIMITED-68S96W /1SESE,
Location ID: 334368



Photo #3183 No public access.



Yellow line indicates 110 yards from access road to private driveway. Mail box at private driveway can be seen in photo #3178 and #3179.

