

Inspection Photos

API: 071-09559

Operator: OGRIS OPERATING LLC

Inspection Date: 3/11/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09559 | Date: 3/11/2021

Inspection Photos



Photo 1. Facing east toward the location. The location is stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09559 | Date: 3/11/2021

Inspection Photos



Photo 2. Sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09559 | Date: 3/11/2021

Inspection Photos




Photo 3. There is oil stained soil at wellhead and engine.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09559 | Date: 3/11/2021

Inspection Photos



Photo 4. Facing toward the pit. Freeboard marker is installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09559 | Date: 3/11/2021