

Inspection Photos

API: 071-07375

Operator: OGRIS OPERATING LLC

Inspection Date: 3/11/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07375 | Date: 3/11/2021

Inspection Photos



Photo 1. Facing southeast toward the location. The location is stabilized and vegetation is well established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07375 | Date: 3/11/2021

Inspection Photos



Photo 2. Facing toward the well.



Inspection Photos



Photo 3. Well sign is posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07375 | Date: 3/11/2021