

Inspection Photos

API: 071-08065

Operator: OGRIS OPERATING LLC

Inspection Date: 3/11/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08065 | Date: 3/11/2021

Inspection Photos



Photo 1. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08065 | Date: 3/11/2021

Inspection Photos



Photo 2. The electric fence around the pit is in disrepair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08065 | Date: 3/11/2021

Inspection Photos



Photo 3. The door on the shed is swinging open. Metal panel laying at entrance way. This need to be repaired or removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08065 | Date: 3/11/2021

Inspection Photos



Photo 4. There is oil stained soil under the engine skid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08065 | Date: 3/11/2021