

Final Reclamation Inspection

March 10, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 447038

Inspection Document #: 697502672

Weld County, CO

NENE Section 10 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: ROSKOP 10-1,7,8, C 10-17 Tank battery

Location ID: 447038



Photo 1. Aerial imagery from 2019. Photo illustrates the former ROSKOP 10-1,7,8, C 10-17 Tank battery (red circle). This location is inside of the pivot circle.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502672

Inspection Photos

Location Name: ROSKOP 10-1,7,8, C 10-17 Tank battery

Location ID: 447038



Photo 2. Photo taken from the eastern tank battery location, facing North. Photo illustrates all equipment has been removed from the tank battery. However, it does not appear the tank battery was properly contoured to the surrounding area and does not have any establishment of alfalfa along the northeastern portion of the location.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Number: 697502672

Inspection Photos

Location Name: ROSKOP 10-1,7,8, C 10-17 Tank battery

Location ID: 447038



Photo 3. Photo taken from the eastern tank battery location, facing West. Photo illustrates some establishment of alfalfa but bare patches are evident.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502672

Inspection Photos

Location Name: ROSKOP 10-1,7,8, C 10-17 Tank battery

Location ID: 447038



Photo 4. Photo taken from the central tank battery location, facing South. See comments under Photo 3.



Inspection Photos

Location Name: ROSKOP 10-1,7,8, C 10-17 Tank battery

Location ID: 447038



Photo 5. Reference crop vegetation.

