

Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 1 – Pumping Unit

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Colorado Oil and Gas Conservation Commission
40.65538, -104.31486, 4837.8ft, 181°
03/11/2021 10:01:27



Colorado Oil and Gas Conservation Commission
40.65495, -104.31495, 4855.2ft, 151°
03/11/2021 10:02:00

Photo 3 – Separators

Photo 4 – Tank Battery

Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 5 – Debris in Pasture SE of Pumping Unit

Photo 6 – Missing NFPA Label

Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 7 – Tank Battery Sign

Photo 8 – Stained Soil spots at Tank Battery