

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/22/2021

Submitted Date:

03/22/2021

Document Number:

699502387

FIELD INSPECTION FORM

Loc ID 453711	Inspector Name: MEDINA, JUSTIN	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 6 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 47120 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Address: P O BOX 173779 City: DENVER State: CO Zip: 80217-				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453704	WELL	PR	11/01/2018	OW	123-46259	QUARTER CIRCLE 24-11HZ	PR
453705	WELL	PR	11/01/2018	OW	123-46260	QUARTER CIRCLE 24-8HZ	PR
453706	WELL	PR	12/18/2018	OW	123-46261	QUARTER CIRCLE 24-10HZ	PR
453707	WELL	PR	12/18/2018	OW	123-46262	QUARTER CIRCLE 24-9HZ	PR
453708	WELL	PR	12/16/2018	OW	123-46263	QUARTER CIRCLE 24-6HZ	PR
453709	WELL	PR	12/23/2018	OW	123-46264	QUARTER CIRCLE 24-1HZ	PR
453710	WELL	PR	11/01/2018	OW	123-46265	QUARTER CIRCLE 24-5HZ	PR
453712	WELL	PR	12/22/2018	OW	123-46266	QUARTER CIRCLE 24-2HZ	PR
453713	WELL	PR	12/22/2018	OW	123-46267	QUARTER CIRCLE 24-3HZ	PR
453714	WELL	PR	12/16/2018	OW	123-46268	QUARTER CIRCLE 24-7HZ	PR
453715	WELL	PR	12/22/2018	OW	123-46269	QUARTER CIRCLE 24-4HZ	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type LOCATION

Comment: 6' chain link with barb wire / Red AG fencing.

Corrective Action:

Date:

Equipment:

corrective date

Type: LACT

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Horizontal Separator

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

11

Comment:

Corrective Action:

Date:

Type: Plunger Lift

11

Comment:

Corrective Action:

Date:

Type: Pig Station

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

11

Comment:

Corrective Action:

Date:

Type: Bird Protectors

12

Comment:

Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Automation / Electric		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with oil tank.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: <u>453704</u>	Type: <u>WELL</u>	API Number: <u>123-46259</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453705</u>	Type: <u>WELL</u>	API Number: <u>123-46260</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453706</u>	Type: <u>WELL</u>	API Number: <u>123-46261</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453707</u>	Type: <u>WELL</u>	API Number: <u>123-46262</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453708</u>	Type: <u>WELL</u>	API Number: <u>123-46263</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453709</u>	Type: <u>WELL</u>	API Number: <u>123-46264</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453710</u>	Type: <u>WELL</u>	API Number: <u>123-46265</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453712</u>	Type: <u>WELL</u>	API Number: <u>123-46266</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453713</u>	Type: <u>WELL</u>	API Number: <u>123-46267</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453714</u>	Type: <u>WELL</u>	API Number: <u>123-46268</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453715</u>	Type: <u>WELL</u>	API Number: <u>123-46269</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Producing Well

Comment: <u>PR</u>	
Corrective Action: <u></u>	Date: <u></u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were overcast, cold, calm, recent snow.	medinaj	03/22/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502388	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5383371