

Inspection Photos
Operator: Simcoe
Facility: 067-08776
Date: 3/16/2021



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area facing northward. Revegetation is progressing with rubber rabbitbrush and smooth brome.



Musk thistles

03.16.2021

Photo 3. View of musk thistles observed along the access road



Photo 4. View of reference area comprised of pinyon and juniper woodland with sagebrush understory, James galleta



Photo 5. View of closed gate after leaving location.