

Inspection Photos  
Operator: Simcoe  
Facility: 067-07128  
Date: 3/16/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western fill slope facing southward. Revegetation is progressing with dense sagebrush shrubland with understory of grasses such as western wheatgrass and crested wheatgrass.





Photo 3. View of reference area comprised of sagebrush shrubland with understory of western wheatgrass and crested wheatgrass.