

Inspection Photos

Loc#334910

Operator: Caerus

Insp#: 692403233

Insp Date: 3/17/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

March 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Rose Ranch Loc#334910



Photo#2:
Interim area.



Photo#3:
Slope on South end of site.

March 17, 2021