

Inspection Photos

Loc#334622

Operator: Caerus

Insp#: 692403237

Insp Date: 3/17/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

March 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Rose Ranch Loc#334622



Photo#2:
View along berm.



Photo#3:
View along berm.

March 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Rose Ranch Loc#334622



Photo#4:

Areas no longer needed for use that could be reclaimed.

March 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#5:

Areas no longer needed for use that could be reclaimed.

Caerus Rose Ranch Loc#334622



Photo#6:
Aerial view of Location.

March 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Rose Ranch Loc#334622