

Inspection Photos

Loc#334582

Operator: Caerus

Insp#:692403242

Insp Date: 3/17/21





Photo#1:
Overview of Location from entry.

March 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Rose Ranch Loc#334582



Photo#2:
View to West over site.



Photo#3:
Chuff pile at East end of site.

March 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Rose Ranch Loc#334582



Photo#4:
Interim area.

March 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#5:
Interim area.

Caerus Rose Ranch Loc#334582