

Inspection Photos

Loc#334585

Operator: Caerus

Insp#:692403244

Insp Date: 3/17/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry.

March 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus HMU Loc#334585



Photo#2:
View over Pad to South.



Photo#3:
Chuff Pile at North end of site.

March 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus HMU Loc#334585



Photo#4:
Interim area.

March 17, 2021



Photo#5:
Interim area.

Caerus HMU Loc#334585