

Caerus Piceance LLC
G14W
Location # 334610

Mar 23, 2021 at 9:51:26 AM
39.446731,-107.741307 ±9.95m
COGCC



location

Mar 23, 2021 at 9:52:58 AM
39.446491,-107.741478 ±4.75m
COGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
G14W
Location # 334610

Mar 23, 2021 at 9:52:47 AM
39.446491,-107.741478 ±4.75m
COGCC



location

Mar 23, 2021 at 9:54:07 AM
39.446193,-107.741330 ±4.73m
COGCC



Lack of stabilization / compaction



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
G14W
Location # 334610

Mar 23, 2021 at 9:54:36 AM
39.446294,-107.741313 ±4.73m
COGCC



Mar 23, 2021 at 9:51:18 AM
39.446814,-107.741256 ±30.48m
COGCC



Lack of stabilization / compaction



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Caerus Piceance LLC
G14W
Location # 334610**

Mar 23, 2021 at 9:51:38 AM
39.446633,-107.741328 ±5.50m
COGCC



Lack of stabilization / compaction

Mar 23, 2021 at 11:48:25 AM
39.449352,-107.733106 ±33.51m
COGCC



Access road entrance from CR 319 shows signs of tracking



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
G14W
Location # 334610

Mar 23, 2021 at 11:48:30 AM
39.449352,-107.733106 ±33.51m
COGCC



Mar 23, 2021 at 11:48:43 AM
39.449352,-107.733106 ±33.51m
COGCC



Access road entrance from CR 319 shows signs of tracking



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Caerus Piceance LLC
G14W
Location # 334610**

Mar 23, 2021 at 11:49:09 AM
39.449317,-107.732863 ±4.71m
COGCC



Mar 23, 2021 at 11:49:44 AM
39.449409,-107.732909 ±4.71m
COGCC



Access road entrance from CR 319 shows signs of tracking



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources