

Caerus Piceance LLC
I15W
Location # 334635

Mar 23, 2021 at 10:08:11 AM
39.444964,-107.754491 ±45.07m
COGCC



location

Mar 23, 2021 at 10:08:15 AM
39.444964,-107.754491 ±45.07m
COGCC



location

Caerus Piceance LLC
I15W
Location # 334635

Mar 23, 2021 at 10:09:48 AM
39.445119,-107.754836 ±4.74m
COGCC



location

Mar 23, 2021 at 10:11:32 AM
39.444854,-107.755610 ±4.77m
COGCC



location

Caerus Piceance LLC
I15W
Location # 334635

Mar 23, 2021 at 10:08:45 AM
39.445056,-107.754403 ±4.78m
COGCC



Mar 23, 2021 at 10:08:55 AM
39.445133,-107.754315 ±4.74m
COGCC




Lack of stabilization / compaction

Caerus Piceance LLC
I15W
Location # 334635



Lack of stabilization / compaction

Caerus Piceance LLC
I15W
Location # 334635



Lack of stabilization / compaction

Caerus Piceance LLC
I15W
Location # 334635

Mar 23, 2021 at 10:17:23 AM
39.445408,-107.754083 ±32.80m
COGCC



Mar 23, 2021 at 10:17:10 AM
39.445408,-107.754083 ±32.80m
COGCC



Access to location



Caerus Piceance LLC
I15W
Location # 334635

Mar 23, 2021 at 11:48:17 AM
39.449352,-107.733106 ±33.51m
COGCC



Mar 23, 2021 at 11:48:30 AM
39.449352,-107.733106 ±33.51m
COGCC



Access road entrance from CR 319 shows signs of tracking



Caerus Piceance LLC
I15W
Location # 334635



Access road entrance from CR 319 shows signs of tracking

Caerus Piceance LLC
I15W
Location # 334635



Access road entrance from CR 319 shows signs of tracking