



Mr. Phillip Porter  
PDC Energy Inc.  
4000 Burlington Avenue  
Evans, Colorado 80620

October 20, 2020

**RE: Vegetation Assessment Report (Final Reclamation Completion Notice)**  
**COGCC Location Information: ARTIST-65N67W /11NWN (Location I.D. 330118)**  
**Operator Location Information: ARTIST 11-12 Well (API# 05-123-18431)**  
**PDC Energy Inc. (Operator: 69175)**

Dear Mr. Porter:

Apex Companies, LLC (Apex) is presenting this letter to PDC Energy Inc. (PDC) documenting the results of a vegetation assessment that demonstrates successful completion of final reclamation efforts, per Colorado Oil & Gas Conservation Commission (COGCC) Rule 1004, on the above-referenced locations. Attached is a topographic location map and a vegetation survey site map with additional location information.

Site visits, project correspondence and documentation, and the completed site assessment confirmed that the location has been final reclaimed, with no evidence of unrestored subsidence over two years. Based on the results of the survey, final reclamation, as defined by COGCC rules and regulations, has been achieved. Photographs exhibiting current site conditions are attached, along with the site map that illustrates the photo points.

On May 18, 2020 the location was visited and four photographs documenting current site conditions were taken. These photographs show that all activities disturbing the ground have been completed, and all disturbed areas have been compacted, covered, graveled, and stabilized in such a way as to minimize erosion.

The landowner's designated final land use has changed, and the surface has been rezoned from agricultural to industrial. The disturbance area is within the Anchor Point RV and Boat Storage facility, where weed management and maintenance of stabilized surfaces are ongoing.

Sincerely,

**Apex Companies, LLC**

A handwritten signature in cursive script, reading 'Carolyn Craveiro de Sá'.

Carolyn Craveiro de Sá  
Environmental Scientist  
720-537-5478

[Carolyn.CraveirodeSa@apexcos.com](mailto:Carolyn.CraveirodeSa@apexcos.com)

**Attachments:**

1. Topographic Location Map
2. Vegetation Survey Site Map
3. Vegetation Assessment Photo Log






# Topographic Location Map

PDC Energy INC

ARTIST 11-12 Well  
(API# 05-123-18431)







## Vegetation Survey Site Map

PDC Energy INC

ARTIST 11-12 Well  
(API# 05-123-18431)

● Vegetation Photo Point

→ Directional Photos

Legal Description: NWNE, Sec. 11, T5N-R67W

Lat/Long: 40.419906/-104.857325

County: Weld

Land Use: Industrial

Inspector: A. Roll

Assessment Date: 05/18/2020

Aerial Imagery Date: 09/12/2018

*\*Please reference coordinate disclaimer on the photo log pages.*





# Vegetation Assessment Photo Log

Date Completed - 05/18/2020

Client - PDC Energy Inc.

Operator Location Information (API) - **ARTIST 11-12 Well (05-123-18431)**



Photo Point A: North of Disturbance - Facing South



Photo Point B: South of Disturbance - Facing North



Photo Point C: West of Disturbance - Facing East



Photo Point D: East of Disturbance - Facing West

\*Geographic coordinates provided in the borders of all attached photos are based on points identified by the mobile phone or tablet which collected the photo. Coordinate accuracy in this format is typically no greater than 5 meters, while the points illustrated in the site diagram associated with this submittal were collected with a high accuracy GPS unit with sub-meter accuracy. Discrepancies between the site diagram and photo coordinates will exist.



## Vegetation Assessment Photo Log

Client - **PDC Energy Inc.**

Date Completed - 05/18/2020

Operator Location Information (API) - **ARTIST 11-12 Well (05-123-18431)**



Photo Point E: Reference Crop Vegetation - Facing East - Southeast