

Inspection Photos
Operator: Simcoe
Facility: 067-07526
Date: 3/16/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope facing northward. Revegetation is progressing with Indian ricegrass, smooth brome, and rubber rabbitbrush.



Photo 3. View of the southern project area facing westward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of shrubs such as serviceberry, mountain mahogany, sagebrush, as well as grasses and forbs such as Indian ricegrass and penstemon.