

## Inspection Photos

Location Name: URSA OPERATING COMPANY LLC Watson Ranch B Pad /,  
Location ID: 440705



**Photo #3211 from entrance to location.**

**Photo #3212 from entrance to location**

## Inspection Photos

Location Name: URSA OPERATING COMPANY LLC Watson Ranch B Pad /,  
Location ID: 440705



**Photo #3213 from entrance to location.**

**Photo #3214 from entrance to location**

## Inspection Photos

Location Name: URSA OPERATING COMPANY LLC Watson Ranch B Pad /,  
Location ID: 440705



**Photo #3225 Unused chemical tank by wellheads.**



**Photo #3215 Location lacks stabilization.**

## Inspection Photos

Location Name: URSA OPERATING COMPANY LLC Watson Ranch B Pad /,  
Location ID: 440705



**Photo #3220 Location lacks stabilization.**



**Photo #3225 Location lacks stabilization.**

## Inspection Photos

Location Name: URSA OPERATING COMPANY LLC Watson Ranch B Pad /,  
Location ID: 440705



**Photo #3222 Location lacks stabilization.**



**Photo #3223 No form of tracking control at entrance to location.**

## Inspection Photos

Location Name: URSA OPERATING COMPANY LLC Watson Ranch B Pad /,  
Location ID: 440705



**Photo #3224 No form of tracking control at entrance to location**