

Inspection Photos
Location Name: North Platte 41-34 Pad
Location ID: 413974



Photo #1 Well

Photo #2 Well

Inspection Photos
Location Name: North Platte 41-34 Pad
Location ID: 413974



Photo #3 Well

Photo #4 Stained Soil

Inspection Photos
Location Name: North Platte 41-34 Pad
Location ID: 413974



Photo #5 Mechanical Conditions

Photo #6 Mechanical Conditions

Inspection Photos
Location Name: North Platte 41-34 Pad
Location ID: 413974



Photo #7 Removed Unused Equipment

Photo #8 New Placard/ Sign