

Inspection Photos
Location Name: State Antelope P-32 Pad
Location ID: 432677



Photo #1 Location



Photo #2 Removed Trash

Inspection Photos
Location Name: State Antelope P-32 Pad
Location ID: 432677



Photo #3 Stained Soil



Photo #4 Mechanical Conditions

Inspection Photos
Location Name: State Antelope P-32 Pad
Location ID: 432677



Photo #5 Mechanical Conditions



Photo #6 Mechanical Conditions

Inspection Photos
Location Name: State Antelope P-32 Pad
Location ID: 432677



Photo #7 Mechanical Conditions



Photo #8 Stained Soil

Inspection Photos
Location Name: State Antelope P-32 Pad
Location ID: 432677



Photo #9 Removed Trash



Photo #10 Removed Trash



Inspection Photos
Location Name: State Antelope P-32 Pad
Location ID: 432677



Photo #11 Lid on vault

Inspection Photos
Location Name: State Antelope P-32 Pad
Location ID: 432677




Photo #12 Bradenhead abatement system



Photo #13 Bradenhead abatement system