

Inspection Photos
Location Name: State Pronghorn 44-32 Pad
Location ID: 441121



Photo #1 Location

Inspection Photos
Location Name: State Pronghorn 44-32 Pad
Location ID: 441121



Photo #2 Removed Stained Soil

Photo #3 Removed Stained Soil

Inspection Photos
Location Name: State Pronghorn 44-32 Pad
Location ID: 441121



Photo #4 Removed Stained Soil

Photo #5 Removed Stained Soil

Inspection Photos
Location Name: State Pronghorn 44-32 Pad
Location ID: 441121



Photo #6 Repaired Berm

Photo #7 Repaired Berm

Inspection Photos
Location Name: State Pronghorn 44-32 Pad
Location ID: 441121



Mar 24, 2021 at 12:50:07 PM
+40.3514, -104.2278
Weld
Colorado Oil & Gas Conservation Commission



Mar 24, 2021 at 12:50:55 PM
+40.3516, -104.2274
Weld
Colorado Oil & Gas Conservation Commission

Photo #8 Fixed Leak

Photo #9 Repaired Fence

Inspection Photos
Location Name: State Pronghorn 44-32 Pad
Location ID: 441121



Photo #10 Removed Unused Equipment



Photo #11 Mechanical Condition

Inspection Photos
Location Name: State Pronghorn 44-32 Pad
Location ID: 441121



Photo #12 Stained Soil



Photo #13 Oily waste has been removed

Inspection Photos
Location Name: State Pronghorn 44-32 Pad
Location ID: 441121



Photo #14 Removed Stained Soil



Photo #15 Removed Unused Equipment

Inspection Photos
Location Name: State Pronghorn 44-32 Pad
Location ID: 441121



Photo #16 Marked Riser



Photo #17 Marked Riser

Inspection Photos
Location Name: State Pronghorn 44-32 Pad
Location ID: 441121



Photo #18 Marked Riser



Photo #19 Marked Riser