

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2021

Submitted Date:

03/25/2021

Document Number:

699103292

FIELD INSPECTION FORM

Loc ID 447613 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447614	TANK BATTERY	AC	09/08/2016		-	LEHFELDT C 27-15,16	SI

General Comment:

This is a follow up to FIRR #402638823. CA has been corrected.

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 447614 Type: TANK API Number: - Status: AC Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 3/25/21 at approximately 0705hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR document #402638823 at Lehfeltd C 27-15, 16 Tank Battery of Noble Energy, at Facility ID # 447614 in Weld County, Colorado. During this inspection the compliance issue has been corrected to comply with COGCC rules. See attached photos. This is a summary of inspection report.</p>	burnsa	03/25/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103293	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5385914