

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2021

Submitted Date:

03/25/2021

Document Number:

699103294

**FIELD INSPECTION FORM**

Loc ID 447438 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447439	TANK BATTERY	AC	08/26/2016		-	DINNEL 01,03, C26-20	SI

**General Comment:**

This is a follow up to FIRR #402637596. CA has been corrected.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 447439 Type: TANK API Number: - Status: AC Insp. Status: SI**Idle Well**Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI Facility

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary  On Thursday 3/25/21 at approximately 0759hrs, I, Inspector Adam Burns,  Conducted an on-site inspection to FIRR document #402637596 at Dinnel 01,03 C 26-20  Tank Battery of Noble Energy, at  Facility ID # 447439 in Weld County, Colorado.  During this inspection the compliance issue has been corrected to comply with COGCC  rules.  See attached photos.  This is a summary of inspection report.</p>	burnsa	03/25/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103295	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5385915">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5385915</a>