

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/25/2021

Submitted Date:

03/25/2021

Document Number:

699103296

**FIELD INSPECTION FORM**
 Loc ID 329664 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447194	TANK BATTERY	AC	08/05/2016		-	SITZMAN-64N64W 27SENE	AC

**General Comment:**

This is a follow up to FIRR #402638836. CA has been corrected.

**Location**Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 447194 Type: TANK API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: AC

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 3/25/21 at approximately 0824hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR document #402638836 at Sitzman-64N64W27SENE Tank Battery of Noble Energy, at Facility ID # 447194 in Weld County, Colorado.</p> <p>During this inspection the compliance issue has been corrected to comply with COGCC rules.</p> <p>See attached photos.</p> <p>This is a summary of inspection report.</p>	burnsa	03/25/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103297	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5385916">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5385916</a>