

## Inspection Photos

**Location Name: CAERUS PICEANCE LLC Orchard Unit /28-6 (E28OU),**

**Location ID: 334187**



**Photo #3267 from entrance to location.**



**Photo #3268 from entrance to location**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC Orchard Unit /28-6 (E28OU),

Location ID: 334187



**Photo #2367 from inspection #699802190 conducted on 12/2/21.**



**Photo #3269 Location lacks stabilization.**

## Inspection Photos

**Location Name: CAERUS PICEANCE LLC Orchard Unit /28-6 (E28OU),**

**Location ID: 334187**



**Photo #3270 No form of tracking control at entrance to location.**