

Inspection Photos
Operator: Simcoe
Facility: 067-08639
Date: 3/23/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area facing northward. Vegetation is largely dormant, but appears to be progressing with western wheatgrass and intermediate wheatgrass.



Photo 3. View of the eastern project area facing northward from the southeastern corner.



Photo 4. View of reference area comprised of open grass field, largely in a grazed/dormant vegetation condition at this time. Perennial grasses such as western wheatgrass as well as unidentified native/dormant forbs are present.