

**Inspection Photos**  
**Operator: Simcoe**  
**Facility: 067-07873**  
**Date: 3/23/2021**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area facing westward from the northeastern corner. Revegetation is progressing with grasses such as sand dropseed and smooth brome.



Photo 3. View of the eastern project area facing southward from the northeastern corner.



Photo 4. View of reference area comprised of grass field in a dormant/grazed condition. Perennial grasses are not identifiable at this time.