







40.11163, -108.21472, 5822.3ft, 22°  
03/23/2021 03:28:10 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Well.**

**Ant Hill 30-31**  
**API: 05-103-09909**





40.11152, -108.21484, 5864.9ft, 213°  
03/23/2021 03:21:41 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Meter building.**

**Ant Hill 30-31**  
**API: 05-103-09909**





40.1116, -108.21484, 5849.0ft, 235°  
03/23/2021 03:21:59 PM





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 5. Leaking lower valve of cracked sight  
glass closed by inspector.**

**Ant Hill 30-31**  
**API: 05-103-09909**





40.11158, -108.21483, 5826.6ft, 322°  
03/23/2021 03:26:39 PM



