

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S95W /7NW4

Location ID: 334073



**Photo #3317 from entrance to location.**



**Photo #3318 Location lacks stabilization.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL-68S95W /7NW4

Location ID: 334073



**Photo #3319 Location lacks stabilization.**



**Photo #3320 No form of tracking control at entrance to location.**