

Inspection Photos

3/25/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430401

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430401



Photo 1: 2006 Google Earth aerial imagery. Photo shows Location prior to pit/location construction.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430401



Photo 2: 2011 Google Earth aerial image. Photo shows constructed Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430401



Photo 3: 2019 COGIS Aerial imagery. Location was closed 1/8/2013; per Rule 1004.a, final reclamation is required within 12 months of closing a facility; final reclamation was required to be completed by 1/8/2014. Photo shows area on the east end of the Location (yellow polygon) that has not been reclaimed, and is being used as a storage area.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430401



Photo 4: Photo taken from the north end of the Location, facing southeast. Photos 4-6 provide an overview of the Location from southeast, south to southwest.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430401



Photo 5: See comments under photo 4.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430401



Photo 6: See comments under photo 4.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430401



Photo 7: Photo taken from the southeast end of the Location, facing north. Photo shows areas on the east end of the Location that have not been reclaimed, and is currently is use as a storage area.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430401



Photo 8: See comments under photo 7. Photo also shows areas that have not been recontoured/regraded/reclaimed.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430401



Photo 9: See comments under photo 7.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430401



Photo 10: See comments under photo 7. Photo also shows tank with chemical stored on the Location.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430401



Photo 11: Continued from photo 10. Fluids and a chemical sheen observed within the container.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430401



Photo 12: See comments under photo 7.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430401



Photo 13: See comments under photo 7.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430401



Photo 14: See comments under photo 7. Photo shows trash debris, including a TEP Sign, within the trash receptacle stored on the Location.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430401



Photo 15: Photo taken from the west end of the Location. Final reclamation of the Location was required by 1/8/2014; at least 6 growing seasons have passed. Photo shows large areas of the Location where uniform, desirable perennial vegetative establishment is not occurring, or not progressing towards 1004 reclamation standards. Additional reclamation work required.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430401



Photo 16: Continued from photo 15. Vegetation observed is predominantly undesirable weedy/annual plant species. There are large areas of the Location where desirable plant establishment was not observed