

Inspection Photos
Location Name: State Seventy Holes P-4 PAD
Location ID: 433884



Photo 1 – Location Sign at Entrance

Photo 2 – Gas Lift Meter House

Inspection Photos
Location Name: State Seventy Holes P-4 PAD
Location ID: 433884



Photo 3 – Separators

Photo 4 – Compressor – Day Tank now has Wildlife Netting

Inspection Photos
Location Name: State Seventy Holes P-4 PAD
Location ID: 433884




Photo 5 – Unmarked Risers at Compressor

Photo 6 – Unmarked Risers East of Compressor

Inspection Photos
Location Name: State Seventy Holes P-4 PAD
Location ID: 433884




Photo 7 – Unmarked Risers at North of Compressor

Photo 8 – Unused Parts at East 2-Phase

Inspection Photos
Location Name: State Seventy Holes P-4 PAD
Location ID: 433884



Photo 9 – Stained Soil

Photo 10 – Wildlife Netting Installed

Inspection Photos
Location Name: State Seventy Holes P-4 PAD
Location ID: 433884



Photo 11 – Risers in the NE Corner have been Marked



Photo 12 – Tank Battery

Inspection Photos
Location Name: State Seventy Holes P-4 PAD
Location ID: 433884



Photo 13 – Wellhead