

Inspection Photos
Location Name: Seventy Holes 44-5 PAD
Location ID: 433304



Photo 1 – Wellheads

Photo 2 – Wellheads

Inspection Photos
Location Name: Seventy Holes 44-5 PAD
Location ID: 433304



Photo 3 – Gas Lift Meter House




Photo 4 – Unmarked Risers at Rack

Inspection Photos
Location Name: Seventy Holes 44-5 PAD
Location ID: 433304





Photo 5 – Unmarked Riser at Maintenance Tank

Photo 6 – Lid is off – Please replace

Inspection Photos
Location Name: Seventy Holes 44-5 PAD
Location ID: 433304



Colorado Oil and Gas Conservation Commission
40.33584, -104.34245, 4474.8ft, 193°
03/23/2021 14:52:01



Colorado Oil and Gas Conservation Commission
40.33518, -104.34254, 4470.6ft, 152°
03/23/2021 14:52:55

Photo 7 – Tank Battery

Photo 8 – Separators and ECDs

Inspection Photos
Location Name: Seventy Holes 44-5 PAD
Location ID: 433304



Photo 9 – Wellheads

Photo 10 – Wellheads