

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2021

Submitted Date:

03/25/2021

Document Number:

699502411

FIELD INSPECTION FORM

Loc ID 457713 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457711	WELL	XX	10/29/2020		001-10200	SCHUH 3-65 21-20 4AH	XX
457712	WELL	DG	12/09/2018	OW	001-10201	Schuh 3-65 21-20 3AH	DG
457714	WELL	XX	10/29/2020		001-10202	Schuh 3-65 21-20 3BH	DG
457715	WELL	XX	10/29/2020		001-10203	SCHUH 3-65 21-20 4BH	XX

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>457711</u>	Type: <u>WELL</u>	API Number: <u>001-10200</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>457712</u>	Type: <u>WELL</u>	API Number: <u>001-10201</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>457714</u>	Type: <u>WELL</u>	API Number: <u>001-10202</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>
Facility ID: <u>457715</u>	Type: <u>WELL</u>	API Number: <u>001-10203</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>

Well Drilling

Rig: Rig Name: Ensign Pusher/Rig Manager: _____
 Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
 Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: WM

Comment: At time of inspection drilling rig had begun to drill earlier in day.
 At time of inspection drilling rig was at approx. 2,700' MD.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were overcast, cold, calm, recent snow.</u>	medinaj	03/25/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699502412	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5389266