

Inspection Photos

API: 073-06504

Operator: WIEPKING-FULLERTON ENERGY

Inspection Date: 3/25/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06504 | Date: 3/25/2021

Inspection Photos



Photo 1. Facing at the fenced location. The fence is not maintained and the gate is down.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06504 | Date: 3/25/2021

Inspection Photos



Photo 2. Center of the location facing north.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06504 | Date: 3/25/2021

Inspection Photos



Photo 3. Center of the location facing south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06504 | Date: 3/25/2021

Inspection Photos



Photo 4. It appears vegetation is establishing at the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06504 | Date: 3/25/2021