

Inspection Photos
Location Name: R & R Farms 5N63W29Q
Location ID: 442583



Photo #1 Location

Photo #2 Wells

Inspection Photos
Location Name: R & R Farms 5N63W29Q
Location ID: 442583



Photo #3 Mechanical Conditions

Photo #4 Stained Soil

Inspection Photos
Location Name: R & R Farms 5N63W29Q
Location ID: 442583



Photo #5 Mechanical Conditions

Photo #6 Stained Soil

Inspection Photos
Location Name: R & R Farms 5N63W29Q
Location ID: 442583



Photo #7 Unused Equipment



Photo #8 Unused Equipment

Inspection Photos
Location Name: R & R Farms 5N63W29Q
Location ID: 442583



Photo #9 Unused Equipment

Photo #10 Unused Equipment

Inspection Photos
Location Name: R & R Farms 5N63W29Q
Location ID: 442583



Photo #11 Unused Equipment

Photo #12 Unused Equipment

Inspection Photos
Location Name: R & R Farms 5N63W29Q
Location ID: 442583



Mar 30, 2021 at 9:22:30 AM
+40.3653, -104.4633

Weld
Colorado Oil & Gas Conservation Commission

Photo #13 Unused Equipment